

Salt River Pima-Maricopa Indian Community

10005 East Osborn Road • Scottsdale, Arizona 85256 Phone (480) 362-7700 • Fax (480) 362-5597

MONTHLY PROJECT PROGRESS UPDATE

Project: <u>ECEC Classroom and Parking Expansion</u>

Issued Date: July 5, 2023 | July-2023 UPDATE

Distribution:

Name		Department/ Company	
X	Tami Brungard	ECEC – Edu Leader	
X	Lekisha Morris	ECEC	
X	Barbara White	ECEC	
X	Melody Herne	Act. Superintendent	
X	Tate Walker	Public Relations Dir.	
X	Deanna Scabby	Edu. Board./ Council	
X	Mikah Carlos	Community Council	

	Name	Department/ Company
X	Kimberly Manuel	ECEC – Policy Council
X	Carmen Briones	ECEC – Policy Council
X	Jennifer Correa	ECEC – Policy Council
X	Brittany Barranca	ECEC – Policy Council
X	Frank Perez	ECEC – Policy Council
X	Rene Uriarte	ECEC – Policy Council
X	Symone Kann	ECEC – Policy Council
X	Felicia Toya	ECEC – Policy Council

Work Completed:

Items

- 1. Parking lot asphalt pavement.
- 2. Building B Addition 1st floor concrete slab.
- 3. Building B Addition CMU vertical walls up to 2nd floor level.
- 4. Central Plant mechanical yard construction site work and footings.


Work anticipated in the next month:


- 1. First (4) Classroom (A146, A147, B147 & C115) renovations are scheduled to start 7/19.
- 2. Building B Addition CMU vertical walls continuation.
- Central Plant mechanical yard concrete slab and CMU wall construction to start.
- 4. Infant playground areas renovation work to start.
- 5. New parking irrigation lines, decomposed granite and rip rap install.
- 6. New door install at exiting wall demo locations for laundry room access.

July 5, 2023 1 | 4

SRP-MIC MONTHLY PROJECT PROGRESS UPDATE

Project Schedule | Three Week Look Ahead





July 5, 2023 2 | 4

SRP-MIC MONTHLY PROJECT PROGRESS UPDATE

Progress Photos:

See attached.

July 5, 2023 3 | 4





Description

Taken Date

06/30/2023 at 12:22 pm

Upload Date

Description

06/30/2023 at 12:23 pm

Uploaded By Carlos Peralta

File Name

D1F8E944-03D2-404B-8B0F-6FFC...

Taken Date 06/30/2023 at 12:22 pm

Upload Date

Uploaded By Carlos Peralta

File Name

06/30/2023 at 12:23 pm 451494CF-8CCC-43A8-8009-7FE9...



Description

Taken Date 06/30/2023 at 11:47 am

Upload Date 06/30/2023 at 11:47 am

Uploaded By Carlos Peralta

File Name

7EF34787-EF06-4F5A-97DE-B659...

Description Irrigation line at Islands and drip system.

Taken Date


06/29/2023 at 01:19 pm

Upload Date 06/29/2023 at 01:19 pm **Uploaded By**

Carlos Peralta

File Name

A9E53A04-ADC0-4A97-AB47-586...







Description

Ronning landscaping Materials at parking lot.

Taken Date	Uploaded By
06/29/2023 at 01:19 pm	Carlos Peralta


Upload Date File Name



Description

Mechanical yard footing steal placement in progress

Taken Date	Uploaded By
06/29/2023 at 10:11 am	Carlos Peralta
Upload Date	File Name
06/29/2023 at 10:12 am	C67ACD77-5385-42D2-97FD-996.



Description

Taken DateUploaded By06/29/2023 at 10:13 amCarlos Peralta

Upload Date File Name

06/29/2023 at 10:13 am 8598203D-614A-46F1-B9D6-D6F...



Description

East stairwells stringer pockets and embeds install in place

Taken Date	Uploaded By
06/29/2023 at 08:28 am	Carlos Peralta
Upload Date	File Name

06/29/2023 at 08:29 am F2CFEFDF-9AFF-4361-B6BF-AC7C...







Uploaded By

Carlos Peralta

F5320316-8B64-4CA9-BF0F-FA55...

Description

New cooling tower pedestals dug out and ready for steel.

Taken Date 06/28/2023 at 11:28 am

06/28/2023 at 11:29 am

Upload Date File Name




Elevator Beam joist on site.

Taken Date 06/28/2023 at 09:36 am

Upload Date 06/28/2023 at 09:36 am

Uploaded ByCarlos Peralta

File Name 58FA013B-28C9-4A89-B873-15DE...



Description

Ready for Compaction inspection at mechanical yard.

Taken Date 06/28/2023 at 11:28 am

Upload Date

06/28/2023 at 11:28 am

Uploaded ByCarlos Peralta

File Name

CF93FD95-670A-4744-8247-492...



Description

Irrigation line.

Upload Date

Taken Date 06/28/2023 at 06:38 am


00/20/2023 at 00.30 an

06/28/2023 at 06:38 am

Uploaded ByCarlos Peralta

File Name

E4345A92-0DC8-435D-8BC8-888...








Description

Irrigation lines and drip system running East and west at main retention.



Uploaded By

Carlos Peralta

Description

Taken Date

06/28/2023 at 06:35 am

Irrigation lines install in progress. Paring lot area.

Taken Date 06/28/2023 at 06:38 am

Carlos Peralta **File Name**

Uploaded By

Upload Date

Upload Date

File Name

0AC7B250-532B-419A-93A4-BCC... 06/28/2023 at 06:35 am



Description

Upload Date

Storm drain pipe under excysting footing.

Description

Storm drain pipe towards retention.

Taken Date 06/27/2023 at 09:30 am **Uploaded By** Carlos Peralta

File Name

06/27/2023 at 09:34 am

F0587912-185B-4709-B3B5-1CA...

Taken Date

Upload Date


Uploaded By Carlos Peralta

06/27/2023 at 09:29 am

File Name

06/27/2023 at 09:29 am

EE363915-BE75-42BE-851D-31E5...







Description

Green marking at new storage bldg.

Taken Date Uploaded By 06/27/2023 at 09:29 am Carlos Peralta

Upload Date File Name

06/27/2023 at 09:29 am



Description

Electrical sleeve for bldg. B

Taken Date Uploaded By 06/26/2023 at 07:16 am Carlos Peralta **Upload Date File Name** 06/26/2023 at 07:27 am 644323C7-12E4-4790-BF0D-70AF...



Description

Irrigation pipe on site.

Taken Date Uploaded By 06/26/2023 at 09:17 am Carlos Peralta

Upload Date File Name

06/26/2023 at 09:17 am 2A7BD220-8<u>C03-42</u>F2-A9A2-9EE...




Description

Safety Barricade elevator shaft.


Taken Date Uploaded By 06/26/2023 at 07:05 am Carlos Peralta


Upload Date File Name

06/26/2023 at 07:05 am F9C12EE5-74BC-48EC-97A1-7665...









Description **Description**

Taken Date 06/22/2023 at 11:34 am

Upload Date

06/22/2023 at 11:37 am

Uploaded By Carlos Peralta

File Name

22E95B45-CA79-474D-8C8E-83A...

Taken Date 06/22/2023 at 11:34 am

Upload Date

06/22/2023 at 11:34 am

Uploaded By Carlos Peralta

File Name

2310B990-142D-486D-8BD2-B74...



Description

Taken Date 06/22/2023 at 11:27 am

Upload Date 06/22/2023 at 11:27 am

Uploaded By Carlos Peralta

File Name 61C581D9-40DF-4B47-B0A5-2FB...

Taken Date

Description

06/22/2023 at 11:26 am

Upload Date

06/22/2023 at 11:26 am


Uploaded By Carlos Peralta

File Name

3F6717FE-E90F-43A4-BF92-62B4...







Taken Date

06/20/2023 at 11:46 am

Uploaded By Carlos Peralta

Upload Date File Name

06/20/2023 at 12:41 pm 4CFF51C8-7F19-4480-953F-19F8...



Description

Door frames installed.

Taken Date Uploaded By 06/19/2023 at 11:52 am Carlos Peralta

Upload Date File Name

06/19/2023 at 11:52 am 8A1DD71C-0F0B-4E65-AEF3-C7C...



Description

Mason starting on elevator shaft.

Taken Date Uploaded By 06/19/2023 at 11:52 am Carlos Peralta

Upload Date File Name

06/19/2023 at 11:52 am DA26504F-B552-48DC-9CA6-B84...




Description

South side doors installed.

Taken Date Uploaded By 06/19/2023 at 11:51 am Carlos Peralta

Upload Date File Name

06/19/2023 at 11:52 am E6267FE8-FE08-4B9F-A2FD-22CE...







Description

Inside the classroom window infill complete

Taken DateUploaded By06/16/2023 at 12:45 pmCarlos Peralta

Upload Date File Name



Description


Existing window frame Removed

 Taken Date
 Uploaded By

 06/16/2023 at 10:47 am
 Carlos Peralta

 Upload Date
 File Name

 06/16/2023 at 10:47 am
 8F53CB56-8FF1-41FC-9937-3890...



Description

Existing window at classroom infill complete

Taken DateUploaded By06/16/2023 at 12:45 pmCarlos Peralta

Upload Date File Name

06/16/2023 at 12:45 pm F0F87D92-FD50-46D7-A27E-D3A...




Description

Old lines been fed from SES to old storage Room.

Taken DateUploaded By06/14/2023 at 11:49 amCarlos Peralta

Upload Date File Name

06/14/2023 at 11:50 am F144B0A1-57BF-477C-8786-52FB...







Description

Upload Date

Underground electrical line from SES to old storage room.

Taken DateUploaded By06/14/2023 at 11:47 amCarlos Peralta

06/14/2023 at 11:47 am 883D5E11-EFF9-423D-807B-BEE1...

File Name



Description

Storm line running East to west.

 Taken Date
 Uploaded By

 06/14/2023 at 11:46 am
 Carlos Peralta

 Upload Date
 File Name

 06/14/2023 at 11:46 am
 1F1A9A88-5DDF-44EA-8C88-AFB...



Description

Storm drain T to retention pond.

Taken DateUploaded By06/14/2023 at 11:46 amCarlos Peralta

Upload Date File Name

06/14/2023 at 11:47 am 73EF3A5D-0A61-43AC-A314-D0B...



Description

Old conduit for Conex.

Taken DateUploaded By06/14/2023 at 11:45 amCarlos Peralta

Upload Date File Name

06/14/2023 at 11:46 am 58E02885-6358-4A28-8D88-EC5...







Description

Power lines north to south.

Taken DateUploaded By06/14/2023 at 11:45 amCarlos Peralta

Upload Date File Name

06/14/2023 at 11:46 am 88BDD2C7-691D-4536-8F3B-04E...



Description

First floor window frames

Taken Date

Uploaded By

06/14/2023 at 11:42 am

Carlos Peralta

Upload Date

File Name

06/14/2023 at 11:43 am D8A7F31C-0EB1-4799-B973-DEA...



Description

Private blue stake complete.

Taken DateUploaded By06/14/2023 at 11:44 amCarlos Peralta

Upload Date File Name

06/14/2023 at 11:46 am AA7E52C0-1A13-4CD5-B1D7-532...




Description

South side bldg.. block first lift.


Taken DateUploaded By06/14/2023 at 11:42 amCarlos Peralta

Upload Date File Name

06/14/2023 at 11:42 am 5E1A9345-D1E1-49A8-9A14-833...







Description

East Parking lot entry complete.

Taken DateUploaded By06/14/2023 at 10:17 amCarlos Peralta

Upload Date File Name

06/14/2023 at 10:17 am 0FFD3E91-E0E6-48D6-A0F2-5B5A...




Description

Bldg. block spreading in progress.

Taken DateUploaded By06/14/2023 at 07:09 amCarlos Peralta

Upload Date File Name06/14/2023 at 07:09 am
F487F21E-8246-45D0-B54B-079C...



Description

East entry asphalt placement in progress.

Taken DateUploaded By06/14/2023 at 09:22 amCarlos Peralta

Upload Date File Name

06/14/2023 at 09:22 am 79630A27-FC4C-4CE7-8C67-325...



Description

Door frames in place.

Taken DateUploaded By06/14/2023 at 07:09 amCarlos Peralta

Upload Date File Name

06/14/2023 at 07:10 am 44CDCFB5-DDBB-4A6C-99E0-586...








Description

Bldg. slab complete and control joints saw cutting in progress.

Taken DateUploaded By06/09/2023 at 12:56 pmSaen Framjee

Upload Date File Name

06/09/2023 at 01:58 pm 8BDC9CDE-2699-4A25-90E7-92A...



Description

Finishers on site.

Taken Date
Uploaded By
06/09/2023 at 05:16 am
Carlos Peralta
Upload Date
File Name

06/09/2023 at 05:17 am FFA656D2-15CE-429E-951C-FC84...



Description

West side stairwell slab.

Taken DateUploaded By06/09/2023 at 05:16 amCarlos Peralta

Upload Date File Name

06/09/2023 at 05:28 am 085F7598-B076-4152-A425-5414...




Description

2:00 AM slab concrete pour CJS


Taken DateUploaded By06/09/2023 at 04:59 amCarlos Peralta

Upload Date File Name

06/09/2023 at 05:22 am AC77B189-8D19-4954-84A7-352...







Description

Slab concrete pour 95 Yards.

Taken Date Uploaded By 06/09/2023 at 04:59 am Carlos Peralta

Upload Date File Name

06/09/2023 at 05:28 am CCF8B6EE-4D1A-4ED5-9FBE-DF8.



Description

Building B Pad With Vapor Barrier and Soil Poison installed. ready for concrete

Uploaded By Taken Date 06/08/2023 at 02:51 pm Saen Framjee **File Name Upload Date** 06/09/2023 at 09:25 am 0E406AC2-C553-4466-AF7A-1499...



Description

Asphalt completed

Taken Date Uploaded By 06/08/2023 at 02:52 pm Saen Framjee

Upload Date File Name

06/09/2023 at 09:25 am D436B2AC-5F4C-4F47-908E-C72...



Description

Vapor Barrier.


Taken Date Uploaded By 06/08/2023 at 01:25 pm Carlos Peralta

Upload Date File Name

06/08/2023 at 01:26 pm 2DB6E311-91A0-4D6A-8CDC-31B...







Description

Vapor barrier installed.

Taken Date Uploaded By 06/08/2023 at 01:25 pm Carlos Peralta

Upload Date File Name

06/08/2023 at 01:35 pm



Description

Water test at parking lot.

Taken Date Uploaded By 06/08/2023 at 08:46 am Carlos Peralta **Upload Date File Name** FA7319CA-E3A9-411A-B506-021E... 06/08/2023 at 08:46 am



Description

CMU Block install over door frames.

Taken Date Uploaded By 06/08/2023 at 01:25 pm Carlos Peralta

Upload Date File Name

06/08/2023 at 01:40 pm 0A2124AE-0B76-410B-9FCB-901...



Description

Washout tub on site deliver


Taken Date Uploaded By 06/08/2023 at 08:46 am Carlos Peralta

Upload Date File Name

06/08/2023 at 08:47 am 273A3BB0-D2BF-46E5-8414-669...







Description

Vapor barrier install complete.

Taken DateUploaded By06/06/2023 at 08:32 amCarlos Peralta

Upload Date File Name

06/06/2023 at 10:52 am 99A303FF-60DB-418B-AB45-0DA...




Description

East side.

Taken DateUploaded By06/06/2023 at 07:29 amCarlos Peralta

Upload Date File Name

06/06/2023 at 07:29 am 61EEDC0D-3D1B-480A-9DCA-0A3...



Description

Asphalt install in place parking lot.

Taken DateUploaded By06/06/2023 at 07:29 amCarlos Peralta

Upload Date File Name

06/06/2023 at 07:29 am 3A57857A-7723-49B7-8635-2F22...



Description

SWPPP in place at dirt mountain on the west side.

Taken DateUploaded By06/05/2023 at 09:10 amCarlos Peralta

Upload Date File Name

06/05/2023 at 12:46 pm D40ED923-98E1-4CE9-BF9B-B36...







DescriptionBuilding B Ready for Concrete

Taken DateUploaded By
06/02/2023 at 12:15 pm
Saen Framjee

Upload Date File Name



DescriptionParking lot ready for asphalt

Taken Date
Uploaded By
06/02/2023 at 12:14 pm
Saen Framjee
Upload Date
File Name

06/02/2023 at 01:31 pm 8625FBC7-5D4D-48C4-908B-C9A...



DescriptionBuilding B being prepped for Concrete

Upload Date

Taken DateUploaded By06/02/2023 at 12:15 pmSaen Framjee

06/02/2023 at 01:31 pm 77B8A6C2-48B9-4326-988C-794

File Name



DescriptionArial of parking lot with AB ready for asphalt

Taken DateUploaded By
06/02/2023 at 12:14 pm
Saen Framjee

Upload Date File Name06/02/2023 at 01:31 pm F07E8C6B-F274-41C9-AB69-0CE5...







Description

Underground plumbing West bathroom

Taken DateUploaded By06/02/2023 at 06:44 amCarlos Peralta

Upload Date File Name

06/02/2023 at 06:46 am 3B1B0796-FE5F-4BEB-A382-D62...




Description

AB Bldg.. B Compaction to follow.

Taken DateUploaded By06/01/2023 at 06:37 amCarlos Peralta

Upload Date File Name

06/01/2023 at 06:50 am 37064989-869F-411C-9A0F-A67C...



Description

Conveyer belt Spreading AB bldg.B

Taken DateUploaded By06/01/2023 at 06:37 amCarlos Peralta

Upload Date File Name

06/01/2023 at 06:44 am 18606E2A-2B5F-4798-96E6-C15A...

SRP-MIC MONTHLY PROJECT PROGRESS UPDATE

Attachments:

Item/s

1. None

July 5, 2023 4 | 4